

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/DFS/MS/2021/1926

Dated: - 20/09/2021

To,

Senior Engineer (E) Health
PWD, GNCTD
2nd Floor, M.S.O Building,
IP Estate, New Delhi-11002


Sub.- Issue of F.S.C in r/o Acharya Bhikshu Govt. Hospital, Moti Nagar, New Delhi-110015.

Sir,

Please refer to your letter no. 23 (Misc) / Superintending Engineer (v.) M/s PWD/21-22/1139 Dated 19/08/2021 on the subject cited above. In this connection, it is to inform you that the Hospital Building was inspected by the officer concerned of this department on dated 28/08/2021 in the presence of Sh. Rajiv Kumar (AE Civil) And observed that Hospital management has not complied the shortcomings issued by this department Vide letter no. F6/DFS/MS/2021/WZ/Hospital/749 Dated 07/04/2021 (Copy In closed)

In view of above, F.S.C cannot be considered at this stage & till such time, occupancy of Hospital Building is at your risk & responsibility.

Yours Faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
(West Zone)

Copy to: -

1. Medical Superintendent Acharya Bhikshu Govt. Hospital, Moti Nagar, New Delhi- 110015
2. Executive Engineer P.W.D, 2nd Floor, M.S.O Building, I.P Estate, New Delhi- 11002

C/150

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No.

FD/DP3/MS/2.21/W2/Hospital/794

Dated:

07/04/2021

To,

The Medical Superintendent,
Acharya Bhikashu Hospital,
Moti Nagar, New Delhi-110015

Sub:- Joint Inspection report in respect of Acharya Bhikshu Hospital, Moti Nagar, New Delhi- 110015.

Sir,

With reference to the above subject a Joint inspection of Acharya Shree Bhikshu Govt. Hospital Located at Moti Nagar, New Delhi was carried out by the officer concerned from Delhi Fire Service, PWD & Hospital Authority on 03/04/2021. During inspection, It has been observed that the Hospital Building is comprised of Basement + Ground & Three upper floors.

The following shortcoming was observed:-

S. No.	Shortcomings	Status
1	Fire pump are not in auto mode due to leakage in pipelines.	Rectified
2	Ventilation system provided in basement but not functional.	Rectified
3	Entire corridor in basement is found blocked.	Rectified
4	Fire check door is removed in staircase at some places of basement & upper floor.	Provisioning of FCD is under progress
5	Detection system is removed at some places like conference hall etc.	Rectified
6	Sealing of electrical shaft is not provided.	Rectified
7	U.P.S. room opening in the staircase of basement shall be segregated with Fire check door.	Rectified

You are requested to comply the above mentioned shortcomings & submit the point wise compliance to this department for further necessary action. Till such time, occupancy of hospital building is at your risk & responsibility.

Yours faithfully

(Atul Gang)
Director
Delhi Fire Service

Copy to:

1. Sh. Anil Govil Assistant Engineer (E) HSW 4, PWD HMED South West Janak Puri Super Specialty Hospital, C-2B, Janak Puri, New Delhi-110058.
2. Executive Engineer, PWD (Electrical) HMED (SW), DAP Lines, Vikas Puri, New Delhi.