GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6 DFS MS 2021 1934

Dated: 21 09 2021

To,

6



Authorized Signatory, Indian Social Institute, Plot No-10, & 12, Lodhi Institutional Area, Lodhi Road, New Delhi-110003.

Subject: Inspection report of M/s Indian Social Institute at Plot No-10, & 12, Lodhi Institutional Area, Lodhi Road, New Delhi-110003 from Fire Safety and means of escape point of view.

Sir,

Please refer to your letter received through Email <u>ID-ashok_pkpc@yahoo.com</u> dated 13/08/2021 on the subject cited above. In this connection it is to inform you that the premises was visited by officer of this deptt. on dated 08/09/2021 in presence of Mr. Shiju Mathew (Administrator) and observed that management has still not complied the office letter issued by this department vide letter No. F6/DFS/MS/2021/172 dated 21/01/2021. (Copy Enclosed).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Copy to :-1. Ex. Engineer, SDMC, Lajpat Nagar, New Delhi.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6 DFS MS 2021 172

Dated: 21 01 2021

To,

Authorized Signatory, Indian Social Institute, Plot No-10, & 12, Lodhi Institutional Area, Lodhi Road, New Delhi-110003.

Subject: Inspection report of M/s Indian Social Institute at Plot No-10, & 12, Lodhi Institutional Area, Lodhi Road, New Delhi-110003 from Fire Safety and means of escape point of view.

Sir,

Please refer to your letter received through Email <u>Id-edisi@isidelhi.org.in dated 02/12/20</u>20 on the subject noted above, in this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 09.12.2020 in the presence of Mr. Shiju Mathew (Administrator) to see the compliance of office letter No. F.6/DFS/MS/BP/94/1367 dated 28.09.1994 and observed that the building comprised of Basement, Ground plus four upper floors and following shortcomings were found:-

- 1. Fire check doors not provided as marked in the plan.
- 2. Smoke managements System found removed in the basement.
- 3. Public address system found removed.
- 4. Stand by pump of capacity 2400LPM found removed.
- 5. Exit signages found removed at some places and lift signages also found removed.
- 6. Fire man grounding switch and communication system in lift not provided.

In view of above NOC/ FSC cannot be considered at this stage.

You are requested to rectify above mentioned shortcoming under intimation to this department for further necessary action please.

Yours faithfully,

Copy to :-

1. Ex. Engineer, SDMC, Lajpat Nagar, New Delhi.