

e-21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/School/NDZ/2021/513

Dated: 24/09/2021

To
The Principal,
Shaheed Bhai Bal Mukund,
Govt. Sarvodaya Vidyalaya, Shankracharya Marg, Delhi-54.

Sub:- Regarding issuance of Fire Safety Certificate in r/o **Shaheed Bhai Bal Mukund, Govt. Sarvodaya Vidyalaya, Shankracharya Marg, Delhi-54.**

Sir,
With reference to email dated 06.07.2021 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (SPM) from this department on 14.09.2021 in the presence of Mr. Mahak Singh (Principal), and it was observed that the school building is comprised of ground + 3 upper floor (Old block). During the inspection following shortcomings were observed:-

1. First Aid Hose reels were found not functional.
2. Fire pump was found not functional.
3. Fire tank was found empty.
4. Exit signages were not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


23/9/21

((Dr. S.K. Tomar))
Dy. Chief Fire Officer
Tel: 011-23412025

Copy to:-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.
 2. Mr. Deepak Mishra, Assistant Engineer (E), PWD Sub-Division 4, Edu. Elect. Edn.1 Div. (N), Zakhira, Rama Road, Delhi-15.
- etc. 24/9