

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/NDZ/2021/ 1963

Dated: 24.09.2021

To

The Addl. Commissioner of Police (Lic),
1st floor, Police Station,
Defence Colony, New Delhi.

Sub: Regarding grant of premises license in r/o Auditorium situated at Dr. Ambedkar International Centre, 15 Janpath, New Delhi.

Sir,

This has a reference to your letter No. 744-48/Joint/CP/Lic(Amst.)/ dated 25.08.2021 on the subject cited above. In this regard, it is to inform you that Auditorium is part of Dr. Ambedkar International Centre building and this department has already issued shortcomings to the building as a whole vide letter No, F6/DFS/MS/NDZ/2020/3103 dated 18.12.2020 , even No. 330 dated 12.02.2021 and No 720 dated 26.03.21 (copy enclosed), which are still not complied.

In view of above, the Fire Safety Certificate (FSC) cannot be issued to Auditorium separately without compliance of all shortcomings issued as earlier.

Yours faithfully,

Encl : As above



(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Chief Architect (Dept. of A& E) , NDMC Palika Kendra , New Delhi
2. Sh. Davinder Singh, Associate Professor, Dr. Ambedkar International Centre, 15, Janpath New Delhi -01

Hand sanitize frequently –wearing of face mask-keep social distance to prevent Covid-19

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/NDZ/2020/ 3101

Dated:- 18.12.2020

To

Sh. Puneet Meena, Sr. Project Executive (Civil)
NBCC Service Ltd., Dr. Ambedkar International Centre
15 Janpath, New Delhi-110001.

Sub: Regarding renewal of Fire Safety Certificate (FSC) in r/o Dr. Ambedkar International Centre, 15 Janpath, New Delhi-110001.

Sir,

This has reference to your e mail <printways@gmail.com. dated 18.11.2020 on the subject cited above. In this regard, it is to inform you that the site was inspected by ADO (CC) & DO (CD) of this department on dated 02.12.2020 in the presence of Mr. Gourav Meena (Project manager, NBCC) & Sh. Punit Meena, Sr. Project Executive (Civil) and the following shortcomings were observed :


1. Electrical shafts are not sealed at each floor.
2. Smoke management system was not integrated with detection /MOEFA.
3. MOEFA found nonfunctional.
4. Exit signages found inadequate.
5. Pressurization in lift lobby found non functional.

In view of above, Fire Safety Certificate (FSC) cannot be considered at this stage. Therefore, you are requested to rectify above shortcomings for further consideration in the matter.

Yours faithfully


(Atul Garg)
Director

011-2341000



Copy To:-

- 1) The Chief Architect
NDMC, Palika Kendra, New Delhi- 01.
- 2) Executive engineer (Bldg),
NDMC, Palika Kendra, New Delhi- 01.