

C-20

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No.F6/DFS/MS/School/NDZ/2021 | 559

Dated: 11/10/2021

To

The Principal,
Bishop Boys Diocesan School,
6-B, Rajpur Road, Delhi-54.

Sub:- Regarding issuance of Fire Safety Certificate in r/o Bishop Boys Diocesan School, 6-B, Rajpur Road, Delhi-54.

Sir,

With reference to letter no. nil dated 11.08.2021 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (SPM) from this department on 04.10.2021 in the presence of Mrs. Monica Massy (Principal), and it was observed that the school building is comprised of ground + 2 upper floor. During the inspection following shortcomings were observed:-

1. First Aid Hose reels was found non functional.
2. Fire pump with auto start facility was found removed.
3. Overhead Tank capacity is 6,000 liters is provided against the requirement of 10,000 liters exclusively for fire fighting.
4. Exit signages were not provided.

In view of above shortcomings, the request for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Local Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


8/10/21

((Dr. S.K. Tomar))
Dy. Chief Fire Officer
Tel: 011-23412025

o/c 
07/10/21

Copy to:-

The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.