

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/EH/NDZ/2021/ 483

Dated:-01.10.2021

To

The Addl. Commissioner of Police (Licensing),  
1<sup>st</sup> Floor, Police Station Defence Colony,  
New Delhi.

Subject: - Online Application ID No.- **2021091821890** in r/o Starbucks Coffee – A Tata Alliance  
(A Unit of Tata Starbucks Pvt. Ltd.) situated at N-16, GF & Mezzanine floor, N-Block,  
Connaught Place, New Delhi.

Sir,

This has a reference to online application ID No.- **2021091821890** dated 18.09.2021 on the subject cited above. In this connection, it is to inform you that the site was inspected by the officers concerned of department on 12/10/2021 in the presence of Ms. Sanju and observed that the shortcomings issued earlier vide letter No F6/DFS/MS/EH/NDZ/2021/122 dated 08.03.2021 ( ID No . 2021020910276 ) are not complied so far. Hence, Fire Safety Certificate (FSC) cannot be issued at this stage.

Therefore, you are requested to take necessary action at your end.

Encl: As above.

Yours faithfully,

(Atul Garg)  
DIRECTOR

Delhi Fire Service

Copy to:-

The Manager,  
Starbucks Coffee – A Tata Alliance (A Unit of Tata Starbucks Pvt. Ltd.),  
N-16, GF & Mezzanine floor, N-Block, Connaught Place, New Delhi.

C-28

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/EH/NDZ/2021/ 122

Dated:-08/03/2021

To

The Deputy Commissioner (Licensing)  
1<sup>st</sup> Floor, Police Station Defence Colony,  
New Delhi.

Subject: - Online Application **ID No.- 2021020910276** in r/o Starbucks Coffee – A Tata Alliance (A Unit of Tata Starbucks Pvt. Ltd.) situated at N-16, GF & Mezzanine floor, Connaught Place, New Delhi.

Sir,

This has a reference to online application ID No.- **2021020910276** dated 12.02.2021 received on the subject cited above. In this connection, it is to inform you that the site was inspected by the officer concerned of department on 02/03/2021 in the presence of Mr. Ajay and the following shortcomings were observed: -

1. 01 staircase of 1.0 m is provided against the requirements of 02 staircase of 1.5 mtr each for mezzanine floor.
2. Alternate exit at ground floor provided less than required width of 1.5 mtr.
3. Overhead water storage tank provided 6,000 liter against the requirements of 20,000 liter capacity .

Hence, Fire Safety Certificate cannot be considered at this stage. Therefore, you are requested to direct the applicant to rectify the above shortcomings for further consideration in the matter.

Yours faithfully

(Atul Garg)  
DIRECTOR  
Delhi Fire Service

Copy to:-

The Manager,  
Starbucks Coffee – A Tata Alliance (A Unit of Tata Starbucks Pvt. Ltd.),  
N-16, GF & Mezzanine floor, N-Block, Connaught Place, New Delhi.