

C-18



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/School/2021/NDZ/ 598

Dated: 01/11/2021

To,

The Principal,  
EDMC Primary School, Hindi II,  
Seelampur Phase III, Welcome,  
Delhi-110053



Subject:- Request for issue NOC for Fire Work.

Sir,

With reference to your email ID [eee2shahnorthzone@gmail.com](mailto:eee2shahnorthzone@gmail.com) dated 04/10/2021 on the subject cited above, it is informed that officer concerned of this department visited the premises on dated 21/10/2021. Principal of the school, Ms. Meera Bai informed that firefighting system is under installation.

In view of the above Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the said shortcoming as issued vide letter No F.6/DFS/MS/2017/1987 dated 02/08/2017 under intimation to this office for further consideration in the matter.

Yours Faithfully,

  
(Atul Garg)  
Director  


Copy to:-

The Director of Education, EDMC,  
Udyog Sadan, Plot No. 419, FIE,  
Patparganj, Delhi-110092

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No. *66/DFSS/MS/2017/1987*

Dated *2/8/17*

To,  
The Principal,  
EDMC Primary School, Hindi II,  
Seelampur Phase III, Welcome,  
Delhi 110053

Sub:- Regarding Issuance Fire Safety Certificate.

Sir,

This is in reference to your letter no. nil dated 29/05/17 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned EDMC Primary School from fire safety point of view in presence of Mrs. Meera Bai, Principal of the School. During the course of inspection, the following points / shortcomings were noticed in the building comprised of ground plus three upper floors.

1. Fire extinguishers were not provided as required.
2. First-Aid hose reels (01 nos.) not provided at each floor as required.
3. A fire pump having 450 LPM output at 40 meters head not provided at terrace as required.
4. Exit Signage were not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

*Vipin Kental*  
(Vipin Kental)  
Chief Fire Officer

Copy to:-  
The Director of Education, EDMC  
Udyog Sadan, Plot No. 419, FIE,  
Patparganj, Delhi 92