

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/EH/2021/NDZ/ 471

Dated: 27/10/2021

To,

Sh. Ashish Agarwal,
M/s Haldiram Ethnic Foods Pvt. Ltd.,
Ground Floor G-3,
Dilshad Garden Main Metro Station,
Delhi-110095

Subject:- Renewal of Fire Safety Certificate.

Sir,

With reference to online letter No. 2021032511653 dated 07/09/2021 on the subject cited above, it is informed that officer concerned of this department inspected the premises in presence of Sh. Mayank, Manager on dated 22/09/2021 and observed that the shortcomings issued vide letter No F.6/DFS/MS/EH/2021/NDZ/342 dated 12/08/2021 have not been complied as yet (The copy of the same is enclosed for your reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours Faithfully,



(Dr. S. K. Tomar)
Dy. Chief Fire Officer



Copy to:-

The Dy. Health Officer,
East Delhi Municipal Corporation,
Health Department, Karkardooma,
South Zone, Shahdara, Delhi

G-29

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/EH/2021/NDZ/ 342

Dated: 12/08/2021

To,

Sh. Ashish Agarwal,
M/s Haldiram Ethnic Foods Pvt. Ltd.,
Ground Floor G-3,
Dilshad Garden Main Metro Station,
Delhi-110095

Subject:- Regarding renewal of Fire Safety Certificate.

Sir,

With reference to your online application No. 2021032511653 dated 31/03/2021 on the subject cited above, it is informed that officer concerned of this department inspected the M/s Haldiram Ethnic Foods Pvt. Ltd. from fire safety point of view in presence of Sh. Mayank, Manager on dated 29/07/2021. The building comprises of ground plus two upper floors (Restaurant running on ground floor and mezzanine floor). During the course of inspection following observations were made:-


1. Hose reel, Wet riser/Down comer system to be extended to cover all areas.
2. Additional staircase of width 1.50 m is required to be provided at mezzanine floor in the building.
3. Alternate exit found blocked.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours Faithfully,



(Dr. S. K. Tomar)
Dy. Chief Fire Officer

OK 

Copy to:-

The Dy. Health Officer,
East Delhi Municipal Corporation,
Health Department, Karkardooma,
South Zone, Shahdara, Delhi