

e-18

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE : NEW DELHI – 110001

No. F6/DFS/MS/School//2021/ 601

Dated 03/11/2021

To,

The Principal
M.C. Primary Co-Ed. School,
Water Works, Wazirabad, Delhi-110054.

Sub: - Regarding issuance of fire safety certificate in r/o M.C. Primary Co-Ed. School, Water Works, Wazirabad, Delhi-110054.

Sir,

This has reference to your letter received through email dated 15.09.2021 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 26.10.2021 in presence of Sh. Shiv Kumar (Guard) to verify the compliance of the shortcomings issued by this department vide letter of even no. 1613 dated 27.06.2016 and observed that the shortcomings have not been complied at all.

Keeping in view of above, Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

Encl: -As above.

(Atul Garg)
Director

Ph: 011-23414250

ATC JP

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/HQ/2016/ 1613

Dated 27/06/2016

To,

The Principal
M.C. Pry. Co.-ed School,
Wazirabad Water Works, Delhi-54

Sub: - Regarding issuance of fire safety certificate in r/o M.C.P. Co-ed School, Wazirabad Water Works, Delhi -110054.

Sir,

Please refer to your letter no. nil dated 06.05.2016 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department to verify the fire safety measures issued vide Director of Education circular dated 01.03.2011/ NBC Part 4 and observed that the school premise is comprised of newly constructed single block of having ground and three upper floor after demolition of ground floor building on a total plot area measuring 848 sq.m. At the time of inspection Sh. Sanjay kumar Sinha, Teacher was also present at site. During the course of inspection observations/ shortcomings made are as under:-

1. Four fire extinguishers provided against the required 06no's of ABC / Co2 type.
2. Hose reel hose not provided.
3. Pump capacity of 450 LPM with 40 mtr head not provided.
4. Exit signage not provided at strategic locations in the building.

Keeping in view of above, fire safety certificate cannot be considered at this stage

Yours faithfully

(Atul Garg)

Chief Fire Officer

Ph: 011-23414250

edu