G H N

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/EH/NDZ/2021/ 5 2 6

Dated 2.2/. /././2021

C127

To,

The Manager, M/S K-Bar & Restaurant, At 7/7 GF, DB Gupta Road, New Delhi – 110055.

Sub: Regarding grant of FSC in r/o M/s K- Bar & Restaurant, 7/7, Ground floor, D.B. Gupta Road, Pahar Ganj, New Delhi.

Sir.

This has reference to your on line ID No. 2021102124809 dated 21.10.21 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned department on 12/11/2021 in the presence of Sh. Ankit (Manager) and the following shortcomings were observed:-

- 1. Hydrants system found removed.
- 2. Overhead water storage tank capacity of 15,000 liters is provided against the requirements of 20,000 liter.
- 3. Exit signages found inadequate.
- 4. Stand by power supply is not provided.

In view of above, the Fire Safety Certificate (FSC) cannot be issued. Therefore, you are requested to direct the applicant to rectify the above shortcomings and resubmit for further consideration in the matter.

Yours faithfully

(**Dr. S.K.Tomar**)

Dy. Chief Fire Officer

Delhi Fire Service

1

Copy to:-

1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defence Colony Police Station, New Delhi.