

C-20

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2021/633

Dated: 07/12/2021

To,

The Vice Principal,
SD Secondary School (GUJRAT),
Kirti Nagar, New Delhi - 110015.


Subject: Regarding Renewal of Fire safety Certificate in respect of SD Secondary School (GUJRAT) located at Kirti Nagar New Delhi – 110015.

Sir,

Please refer to your Email dated 26/10/2021 on the subject captioned above. In this connection, it is to inform you that the said building/premises was re-inspected by the officer concerned of this department on 26/11/2021 in the presence of Sh. Rakesh Babu (Vice Principal) and observed that the shortcomings already communicated by this department vide letter No.F6/DFS/MS/School/MN/2021/155 dated 26/03/2021, (Copy Enclosed) is still not complied.


In view of above Shortcomings the application for Renewal of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The licensing issuing authority/statutorily authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours Faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire officer
Delhi Fire service

Copy to:

1. Directorate of Education, Old secretariat, Delhi – 110054.


04/12/2021

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE:
NEW DELHI – 110001

No.F6/DFS/MS/School/MN/2021/155

Dated: 26/03/2021

To

The Vice Principal,
 SD Secondary school (GUJRAT)
 Kirti Nagar, New Delhi -110015.

Sub:- Inspection report in r/o of SD Secondary School(GUJRAT) Located at Kirti Nagar New Delhi -110015.

Sir,

Please refer to your letter dated 14.01.2021 on the subject cited above. In this connection it is informed that the premise was inspected by the officer concerned of this department on 10.02.2021 in the presence of Sh. Rakesh Babu (Vice principal) to check the workability of existing Fire safety arrangements. During inspection, it has been observed that the said building is comprised of basement, Ground plus one upper floor. The Basement is served by two staircases. Ground & upper floor are served by three staircases. Fire safety arrangements such as Fire Extinguishers, Hose reels, Sprinkler system etc. are provided. However the following shortcoming was observed:-

1. Width of main gate is less than the required width 3.8m (as per letter dated 23/07/2018)

You are requested to comply the above mentioned shortcoming under intimation to this department for further necessary action.

Yours Faithfully

(Dharampal Bhardwaj)
 Dy. Chief Fire officer
 Delhi Fire service

o/c
 24/03/2021

Copy to: -

1. Directorate of Education Old Secretariat Delhi – 110054