

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/2021/645

Dated 13/12/2021

To,

The Principal,
Sarvodaya Kanya Vidyalaya,
Sarai Rohilla, Delhi.

Sub: Regarding grant of FSC in r/o Sarvodaya Kanya Vidyalaya, Sarai Rohilla,
Delhi.

Sir,

This has a reference to your letter no. GBSSS/SR/ dated 14/10/2021 & Email < gbsssarairohilla23646113@gmail.com > on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 02/12/2021 in the presence of Mr. Hirdesh Kumar and observed that shortcomings issued earlier vide letter no. F6/DFS/MS/WZ/2019/5248 dated 29.08.19 & F6/DFS/MS/WZ/2019/6487 dated 29/10/2019(copy enclosed) are still not complied.

In view of above, the application for issuance of fire safety certificate is rejected. The occupancy of building /premises, in absence requisite fire & life safety arrangements, shall be at the risk and liability of the owner/occupier. The statutory authority may take suitable action as deemed fit,

Yours faithfully

Encl: As above


9/12/21

(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Director (Education), Govt. of NCT, Old Sectt. Delhi.

c/s

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2019/ 5248

Dated: 29 / 08/2019

To

The Principal,
Sarvodaya Kanya Vidyalaya,
Sarai Rohilla,
Delhi

Sub: - Inspection report in respect of Sarvodaya Kanya Vidyalaya, Located at Sarai Rohilla (School ID-1208015) Delhi

Sir,


Please refer to your letter no. SKV/SR/2019/80 dated -26/06/2019 on the subject noted above. In this connection, it is informed that the said school premises have been inspected by the officer concerned of this department on 07/08/2019 in the presence of Ms. Chanchal Sharma (V. Principal)

The following shortcoming was observed during the time of inspection:-


1. Entry gate is not accessible for fire tender.
2. Width of Corridor in block 2 varies from 130cm to 197cm against required clear width 1.5m.
3. LPG cylinders are not being used with proper safety precaution it must be used as per DOE Circular no.3298-3398 dated 01-03-2011.
4. Hose Reels found nonfunctional.
5. Two Pumps of 450 lpm found nonfunctional.
6. Exit signage's not provided.

You are requested to comply the above mentioned shortcomings under intimation to this department for further necessary action.

Yours faithfully


(Atul Garg)
Chief Fire Officer
Delhi Fire Service

Copy to:- Director of Education, Old Secretariat, Delhi-110054



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

cl 8

No. F6/DFS/MS/WZ/2019/ 6487

Dated: 28/10/2019

To

The Principal,
Sarvodaya Kanya Vidyalaya,
Sarai Rohilla,
Delhi

Sub: - Inspection report in respect of Sarvodaya Kanya Vidyalaya, Located at Sarai Rohilla (School ID-1208015) Delhi

Sir,

Please refer to your letter SKV/SR/234 dated 27/09/2019 on the subject captioned above. In this connection it is to inform you that the shortcomings has already communicated to you vide this office letter no. F6/DFS/MS/WZ/2019/5248 dated 29/08/2019(Copy enclosed), You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,

Enclosed :- As above

Director,
Delhi Fire Service.

Copy to;- Director of Education, Old Secretariat, Delhi-110054

28/10/19