GOVERNMENT HEADQUARTE

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/EH/2022/SZ/ 270 To. Dated: 29/03/2022

The Manager, M/s Jubilant Foodworks Ltd (Dominos Pizza), GF-WZ-154, Block, Opp. Metro Pillar No.-680, Najafgarh Road, Uttam Nagar, New Delhi-110059.

Sub:-Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o M/s Jubilant Foodworks Ltd (Dominos Pizza), GF-WZ-154, Block, Opp. Metro Pillar No.-680, Najafgarh Road, Uttam Nagar, New Delhi-110059.

Sir,

This has reference to your letter No. Nil dated 07/03/2022 on the subject captioned above. In this connection, it is to inform you that the premise was inspected on 15/03/2022 by the officer concerned of this department in the presence of Sh. Danish Siddiki verify the compliance of shortcomings already communicated by this department vide letter no.F6/DFS/MS/EH/2021/SZ/336 dated 09/08/2021. During the course of inspection it was observed that the shortcomings have not been rectified except point no. 3.

In view of above, the fire safety certificate can not be considered at this stage. You are requested to rectify the shortcomings under intimation to this department for further course of action.

Yours faithfully

(Sunil Chawdhary)

Dy Chief Fire Officer

c-21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/EH/2021/SZ/336

Dated: 09/08/2021

To,

The Joint Commissioner (Lic.) 1st Floor Police Defence Colony, New Delhi.

Sub: -Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o M/s Dilli 59 (A Unit of Aggarwal Traders) WZ-154,G-1, block, Najafgarh Road near metro pillar 680, Uttam Nagar, New Delhi.

Sir,

Please refer to your letter ID No. 2021041212818 dated 14/04/21 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the building to verify the fire safety arrangements in accordance with the rules. At the time of inspection Sh. Rajesh Sharma was present and it was observed that the building is comprised of Basement, stilt, upper ground, first & second floor but restaurant is running at upper ground & first floor and have following shortcomings:-

- 1. An additional staircase shall be provided 1.5 m wide.
- 2. One of the exit shall be 2 m wide instead of 1.7 m in restaurant.
- 3. Fire check door not provided.
- 4. First aid hose reel & down comer system provided but not functional.
- 5. Fire pump having 450 LPM provided but not functional & auto mode.
- 6. Over head water tank 15, 000 liters provided in place of 20,000 liters.
- 7. Exits signage's are not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk & liability of the owner/occupier. The Licensing Authority/Statutory Authority may be take suitable necessary action as deemed fit.

Yours faithfully

DirectorDelhi Fire Service

Copy to:-

H.

The Manager, M/s Dilli 59 (A Unit of Aggarwal Traders) WZ-154, G-1, block, Najafgarh Road near metro pillar 680, Uttam Nagar, New Delhi.