GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001 Dated: 25/03/2022

No.F6/DFS/MS/WZ/2022/GH/237

To.

The Authorized Signatory, M/s. V4 Residency LLP, 62, Samrat Enclave, Kali Mata Mandir, Pitampura, Delhi-110034.

Sub.: -Regarding issuances of fire safety certificate in r/o M/s. V4 Residency LLP Located at 62, Samart Enclave near Kali Mata Mandir, Pitampura, Delhi-110034.

Sir,

Please refer to your email dated 25.02.2022 on the subject cited above. In this connection it is to inform you that the said building have been inspected by the officer concerned of this department on 16.03.2022 in the presence of Sh. Ravi (Manager) to check compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/GH/WZ/2021/672 dated 04.10.2021.

During inspection, it have been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Director

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/WZ/2021 672

Dated 04/ 0/2021

The Addl. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi

Sub.:- Regarding issuance of Fire Safety Certificate in r/o M/s. V4 Residency LLP Located at Property No. 62, Samrat Enclave, Near Kali Mata Mandir, Pitampura, Delhi-110034.

Sir.

This has reference to online application no. 2021081417771 dated 20.08.2021 on the subject cited above. In this connection it is to inform you that the above said Guest House building has been inspected by the officer concerned of this department from Fire safety point of view on 22.09.2021 in the presence of Sh. Amit Rajak (Owner) & Sh. Ravi (Manager). During inspection, it has been observed that the said building is comprised of Basement + Stilt + 04 upper floors.

The following shortcomings have been observed:

- 1. 01 Staircase having width 1 mtr. is provided against requirement of Two Staircases 1.5 mts. Wide at all floors.
- 2. Smoke Management system is not provided in all upper floors.
- 3. Fire Check Doors 1.5 m wide not provided at each floor.
- 4. Carbon Monoxide detectors are not provided in guest room at all upper floors.
- 5. PA system is not provided.
- 6. Automatic Sprinklers not provided in basement.
- 7. 4000 ltrs capacity Overhead water storage tanks for firefighting are provided against requirement of 15,000 ltrs.
- 8. Exit Signs are not provided.

In view of the above shortcoming, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/statutory Authority may take suitable necessary action as deemed fit.

Copy to:-

1. Sh. Amit Rajak, M/s. V4 Residency LLP, Property No. 62, Samrat Enclave, Near Kali Mata Mandir, Pitampura, Delhi-110034.