

C18

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No. F6/DFS/MS/School/2022/NDZ/ 188

Dated: 20/04/2022

To,

The Manager
M/s S.R Public School,
D-62, west Jyoti Nagar, Shahdara,
Delhi-110094.

Subject: -Regarding issuance of Fire Safety Certificate in r/o M/s S.R Public school at D-62, West Jyoti Nagar, Shahdara, Delhi-110094.

Sir,

Please refer to letter. dated 23/03/2022 on the subject cited above. In this regard, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department in presence of Mrs. Lalita (Principal) of the school on dated 12/04/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F6/DFS/MS/School/2019/2216 dated 22/04/19 are yet to be rectified. Copy of the same is enclosed for your ready reference.

Yours faithfully



(Dr. S.K Tomar)
Dy.Chief Fire Officer



Copy to:-

- 1) The Director of Education,
Udyog Sadan, Plot No.419, FIE,
Patparganj Industrial Area, Delhi-110092

09

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2019/ 2216

Dated: 22/4/19

To,

The Manager,
M/s S.R. Public School,
D-62, West Jyoti Nagar, Shahdara,
Delhi 110094

Sub:- Regarding Issuance of Fire Safety Certificate in r/o M/s S.R. Public School at D-62, West Jyoti Nagar, Shahdara, Delhi 110094.

Sir,

This is in reference to your letter No. nil dated 12/02/19 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mrs. Lalita, Principal of the School. During the course of inspection, the following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

1. The width of staircase shall be 1.50 meter or an additional staircase of 0.75 meter shall be provided.
2. First-Aid hose reels (01 nos.) at each floor provided but not functional.
3. A fire pump having 450 LPM output at 40 meters head not provided.
4. Over Head water storage tank 2,000 liters capacity provided at terrace in place of 10,000 liters as required.
5. Exit Signage were not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully



(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92

ole
of