

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/DFS/MS/WZ/BNQT/2022/58

Dated: 12/4/2022

To,

The Joint Commissioner of Police,
Licensing Unit, 1st floor, Police Station,
Defence Colony, New Delhi.
addlep.lic-dl@nic.in

Sub:- Inspection report in r/o Falcon Banquet, (A Unit of SRM Banquet Pvt. Ltd.), Plot no. 17,
Chhatrapati Shivaji Marg, Najafgarh Road, New Delhi- 110015.

Sir,

Please refer to your online application no.:- 2022022202486 dated: - 22/02/2022 on the subject cited above. In this connection it is to inform you that the premises was inspected by officers concerned of this department on 24/03/2022 in the presence of Sh. Siddhant Gupta to see the functioning of fire safety equipments provided in the building.

During inspection, It has been observed that the banquet was running at Ground + 1st & 2nd floor in a building comprised of Basement + Stilt + Ground + Mezzanine + 02 Upper floors was issued FSC vide letter No. F6/DFS/MS/2019/WZ/92 dated 11/01/2019. Fire safety arrangements such as Under Ground Tank, Overhead Tank, Internal Hydrant, First Aid Hose reel, MOEFA, Detection System, D.G. Set, Fire Extinguishers etc provided. However the following shortcomings were observed.

1. Fire check doors found removed.
2. Smoke management system provided but not functional.
3. First-Aid Hose Reels are provided but not functional.
4. Automatic fire detection and alarming system provided but not functional.
5. MOEFA is provided but not functional.
6. Public Address System provided but not functional.
7. Automatic sprinkler systems are provided but not functional.
8. Internal Hydrant are provided but not functional.
9. Ground level Fire Pump of 2280 lpm, Jockey Pump 180 lpm, Alternate pump connection with DG Set & Terrace level pump 900 lpm is provided but not functional.
10. Exit signage's are found removed.
11. Staircases & Lift shall be sealed at basement level.
12. Basement floor is not constructed as per available plan submitted by the management.
13. Plans duly signed by Architect & Owner are not uploaded on MHA portal.

In view of above Shortcomings the application for renewal of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The licensing issuing authority/statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfully

(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

Copy to: -

1. The Owner/ Occupier M/s. Falcon Banquet, (A Unit of SRM Banquet Pvt. Ltd.), Plot no. 17, Chhatrapati Shivaji Marg, Najafgarh Road, New Delhi- 110015. Online ID - 2022022202486 dated 22/02/2022
2. DHO, West Zone, SDMC, Shivaji Enclave, Raja Garden, New Delhi- 110027.
(dhowest zone@gmail.com)