

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No.

FC/DFSI/22/22/1102(Hospital)/888

Dated: 22/04/2022

To,

Sh. Rajan Pathak, J.E.(E), PWD,  
Chacha Nehru Bal Chiktsalaya,  
Geeta Colony, Delhi-110031.

**Sub:- Fire Safety inspection in r/o Chacha Nehru Bal Chiktsalaya, Geeta Colony, Delhi-110031.**

Sir,

Above mentioned premises was inspected by the officer concerned of this department in along with Sh. Narender Pal Singh, Retd. St.O. (Consultant) in presence of Sh. Rajan Pathak, J.E. (E), PWD on dated 18/04/2022 to view the operatibility of Fire Safety arrangements provided in the building and also to see the compliance of office letter communicated by this department on dated 17/01/2021. Fire protection system provided in the building such as Hose reel hose, Hydrants, smoke detectors were randomly checked and found functional at the time of inspection. However some shortcomings were noticed which areas per under:-

1. Sealing of electrical shafts, AHU shafts and other shafts are not done yet.
2. Installation of detectors under false ceiling is not complete yet (Under Progress).
3. Ventilation system in basement was found nonfunctional.

This is for your kind information and necessary action please.

Yours faithfully,

  
(ATUL GARG)  
DIRECTOR.

Copy to:-

1. M.S., Chacha Nehru Bal Chiktsalaya, Geeta Colony, Delhi-110031.