

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

NO. F-6/DFS/MS/Hosp./2022/SZ/ 889

Dated 22/04/2022

To

The Chief Security Officer,  
Administrative Block,  
AIIMS, New Delhi

**Sub:** - Regarding issuance of fire safety certificate in r/o P.C Teaching Block, AIIMS New Delhi.

Sir,

This has reference to your Gmail of dated 26/03/2022 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 07.04.2022 to verify the fire safety measures installed in the building and observed that building is comprised of Four interconnected, Ground Plus Five, Four, Three & Two Upper Floors. During inspection, following points were observed:

1. 06 meters wide motor able road all around the building not provided and tree trimming is also required.
2. Smoke management system in basement found non functional.
3. Yard hydrant system all around the building not provided.
4. Lift signees and floor making are not done.
5. HT, LT Panels and transformer are not provided with required fire protection systems.
6. Basement floor found filled with water logging and it is dangerous for stability of the building.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

  
(ATUL GARG)  
DIRECTOR / DFS

Copy to:

1. The Chairman, NDMC, New Delhi