## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/WZ/2022/ 1054

Dated: 1] /05/2022

110

To,

Sh. D. P. Vashisht, KLJ Tower, B-5, Netaji Subhash Place, Pitampura, Delhi-110034,

## Subject: -<u>Regarding renewal of Fire Safety Certificate in r/o KLJ Tower, Located at</u> <u>Plot no. B-5, Netaji Subhash Place, Pitampura, Delhi-110034.</u>

Sir,

This has refer to your letter no. nil dated 29.03.2022 on the subject cited above. In this connection, it is to inform you that the above said building have been inspected by the officers concerned of this department from fire safety point of view on 22.04.2022 in the presence of Sh. Shiv Kumar (Site Engineer) to check the shortcomings communicated vide this department letter dated 23.03.2022, 17.12.2020 & 02.05.2018.

## The statuses of shortcomings are as under:-

		Status
S. no.	Shortcomings	Not rectified
1	Fire check doors were found removed at some places	
2.	Pressurization Fans of lift shaft & lift lobby not found	Not rectified
	working in auto mode	Not rectified
3.	Sprinkler & Detection systems have been removed in some	Not rectified
	rooms at each floor.	(1) and at

In view of the above shortcomings, Fire Safety Certificate cannot be renewed at this stage. You are advised to rectify the above mentioned shortcomings under intimation to this department for taking further necessary action.

Yours faithfull Garg) Director

Copy to: - The Vice Chairman, DDA, INA Vikas Sadan, New Delhi-110023.