



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001**

Dated: 18/05/2022

No. F6/DFS/MS/School/2022/NDZ/ 231

To,



The Manager
EDMC Nigam Pratibha Vidyalaya,
D-Block, Harsh Vihar,
Delhi-110093.

Subject: -Regarding issuance of Fire Safety Certificate in r/o EDMC Nigam Pratibha
D-Block, Harsh Vihar, Delhi-110093.

Sir,

Please refer to letter.D-382/DDOS/H.V.I/EDU./SH.N/EDMC/2022 dated-16/04/2022 on the subject cited above. In this regard, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department in presence of Mrs. Kaveri(HOS)on dated 10/05/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F6/DFS/MS/School/2019/NDZ/1303 dated 15/03/19 are yet to be rectified. Copy of the same is enclosed for your ready reference.

Yours faithfully


(Dr. S.K Tomar)
Dy.Chief Fire Officer


Copy to:-

- 1) The Director of Education,
Udyog Sadan, Plot No.419, FIE,
Patparganj Industrial Area, Delhi-110092

C-13

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2019/NDZ/ 1303

Dated: 15/03/19

To,

The Vice Principal,
M/s EDMC Primary School
D-Block, Harsh Vihar,
Delhi-110093

Sub:- Regarding Issuance of Fire Safety Certificate in r/o M/s EDMC Primary School at D-Block, Harsh Vihar, Delhi-110093.

Sir,

This is in reference to your letter No. nil dated 16/01/2019 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mr. Vijendra Singh Sagar, Principal of the School. During the course of inspection, the following points / shortcomings were noticed in the building comprised of ground plus three upper floors.

1. First-Aid hose reels (01 nos.) at each floor provided but not functional.
2. A fire pump having 220 LPM provided in place of 450 LPM output at 40 meters head as required.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully


(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy:-

The Director of Education, EDMC,
Udyog Sadan, Plot No.419, FIE,
Patparganj Industrial Area,
Delhi-110092

ele
ek