

C7

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE : NEW DELHI – 110001

No. F6/DFS/MS/School/2022/ 273

Dated 31/05/2022

To,

The Principal
M.C. Primary Co-ed School,
Dhakka Village, Delhi-110009.

Sub: - Regarding issuance of fire safety certificate in r/o M.C. Primary Co-ed School (school I'd No.1253097) located at Dhakka Village, Delhi-110009.

Sir,

This has reference to your letter no. Nil dated 02.05.2022 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 17.05.2022 in presence of Smt. Sudha Pasricha (Incharge) and verify the compliance of the shortcomings/ observations already communicated by this department vide letter of even no. 1631 dated 23.06.2017 and observed that the shortcomings have not been removed so far.

Keeping in view of above, Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

(Anil Gang)
Director

Ph: 011-23414250

etc Op

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

24

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/HQ/ 2017/ *School/1631*

Dated *23/06/2017*

To,

The Principal
M.C. Pry. Co.-ed School,
Dhakka, Delhi-09.

Sub: - Regarding issuance of fire safety certificate in r/o M.C. Pry. Co.-ed School, Dhakka Delhi-09.


Sir,

Please refer to your letter no. nil dated 19.03.2017 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department to verify the fire safety measures issued vide Director of Education circular dated 01.03.2011/ NBC Part 4 and observed that the school premise is comprised of newly constructed single block of having ground and two upper floor. At the time of inspection Smt. Santosh , S.K. was also present at site. During the course of inspection observations/ shortcomings made are as under:-

1. The gate width of 3.50m against requirement of 4.50m wide.
2. Hose reel hose not provided.
3. Pump capacity of 450 LPM with 40 mtr head not provided.
4. Overhead tank capacity of 10,000 ltr not provided.
5. Exit signage not provided at strategic locations in the building.

Keeping in view of above, fire safety certificate cannot be considered at this stage

Yours faithfully



(Atul Garg)

Chief Fire Officer

Ph: 011-23414250

