

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2022/ 283

Dated: 03/06/2022

To,

The Principal,
New Shalimar Public School,
BM-Block, (West), Shalimar Bagh,
New Delhi-110088

Sub: - Regarding Renewal of Fire Safety Certificate in r/o New Shalimar Public School
Located at BM-Block, (West) Shalimar Bagh, New Delhi-110088.

Sir,

Please refer to your letter Outdoor Dairy No. 387 dated 11/04/2022 on the subject cited above. In this connection, it is to inform you that the said building/premises was inspected by the officer concerned of this department on 19/05/2022 in presence of Ms. Neetu Duggal (Principal) to see the functioning of fire safety equipments provided in the building.

During inspection, it has been observed that the above said school is running at Ground + Mezzanine + 01 Upper Floor in a building is comprised of Ground + Mezzanine + 01 Upper Floor was issued FSC vide letter no. F6/DFS/MS/WZ/SCHOOL/2019/491 dated 08/03/2019. Fire Safety arrangements such as Fire Extinguishers, First -Aid Hose reel, Terrace pump, overhead water storage tank etc. have been provided in the building. However, the following shortcomings were observed.

1. First Hose reels are provided but not functional.
2. Internal Hydrants is provided but not functional.
3. Terrace fire pump of 450 lpm & 220 lpm is provided but not functional.
4. Overhead water storage tank 5000ltr provided but found empty.

In view of above Shortcomings the application for Issuance of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The educational authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

Copy to: -

1. The Director, Directorate of Education, old secretariat, Delhi.