

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI- 110001

No. F6/DFS/MS/School/2022/SZ/ 296

Dated: 07/06/2022

To,

The Principal,
Govt. Sarvodaya Bal Vidyalaya No.-1,
Tilak Nagar, New Delhi-110018.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/ Govt. Sarvodaya Bal Vidyalaya No.-1, Tilak Nagar, New Delhi-110018.

Sir,

This has reference to your letter no. SBV/NO1/TN/2022/177 dated 28/04/2022 on the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 24/05/2022 in the presence of Estate Manager to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2019/SZ/293 dated 17/01/2019. During the course of inspection it was observed that the shortcomings have not been rectified except point no. 1 & 4. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully

(Sunil Chawdhary)
Dy. Chief Fire Officer



Copy to:-

1. The Director of Education,
Govt. of NCT of Delhi,
Old Secretariat, New Delhi-110054.

(With a request to take further action as school does not have fire NOC)

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ } 293

Dated: 17/01/19

To,

The Principal,
Govt. Sarvodaya Bal Vidyalaya No.-1,
Tilak Nagar, New Delhi-110018

Sub: - Regarding issuance of Fire Safety Certificate in r/o Govt. Sarvodaya Bal Vidyalaya No.-1,
Tilak Nagar, New Delhi-110018.

Sir,

This has reference to your Letter No. SBV/No.-1/TN/2018/1859 dated 24.11.2018 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 26.12.2018 to see the compliance of the requisite fire safety measures. Sh. N.S Bindra (Estate Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of three blocks namely Main Building Block, Primary Block & Auditorium Block. Main Building block is having ground floor plus two upper floors. Primary block is having ground floor plus one upper floor & Auditorium Block is having ground floor only. The upper floors of Main Building Block are served by four staircases having width 134, 134, 160 & 140 cms. The upper floor of Primary Block is served by two staircases having width 165 & 155 cms. The existing fire protection arrangements such as Fire Extinguishers, Hose Reel System, Fire Pump of 450 LPM (02 no.'s). overhead water storage tank of 10,000 ltrs Exit signs etc. are provided in the premises. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcoming was observed:-

1. Door width is 95 cms (03 no.'s) in Auditorium Block against required 200 cms each.
2. Hose reel system provided but not functional in Main Building block & Hose reel system is not provided in Auditorium Block.
3. Fire pump having capacity 450 LPM (02 no.'s) provided but not functional.
4. Over head water storage tank having capacity 5000 ltrs not provided in Auditorium Block.
5. Illuminated exit signs are not provided in Auditorium Block.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,



(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054