C-29

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/NDZ/2022/ EH 385

Dated:-.06/06./2022

Τo

The Manager
M/S Suvidha Restaurant,
At 7361 Ground Floor of Tourist Hotel,
Qutub Road, Ram Nagar, Pahar Ganj,
New Delhi.

Sub: Regarding issuance of FSC in r/o M/S Suvidha Restaurant at 7361 Ground Floor of Tourist Hotel, Qutub Road, Ram Nagar Pahar Ganj, New Delhi, id no. 2022050709639 dated 08.05.2022.

Sir,

This has reference to online ID No. 2022050709639 dated 08.05.2022 on the subject cited above, it is to inform you that the site was inspected by the officers concerned department on 27/05/2022 in the presence of manager and observed that the shortcomings issued earlier vide letter no. F6/DFS/MS/NDZ/2021/337 dated 09.08.2021 (copy enclosed) are still not complied.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings issued earlier vide aforesaid letter for further consideration in the matter.

Encl. As above.

IMIL

DIRECTOR Delhi Fire Service

Copy to :-

The Joint Commissioner of Police (Lic.), Licensing Unit, Defense Colony Police Station, New Delhi.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/NDZ/2021/337

Dated:-09/08/2021

To

The Manager
M/S Suvidha Restaurant
At 7361 Ground floor of tourist hotel
Qutub Road, Ram Nagar, Pahar Ganj
New Delhi

Sub: Regarding issuance of FSC in r/o M/S Suvidha Restaurant at 7361 Ground floor of tourist hotel round floor, Qutub Road ,Ram Nagar Pahar Ganj, New Delhi

Sir,

This has reference to online ID No. 2021061213792 dated 14.06 21 on the subject cited above, it is to inform you that the site was inspected by the officers concerned department on 19/07/2021 in the presence of Sh. Lokesh and the following shortcomings were observed:-

- 1. Alternate exit of 1.5 meter is not provided.
- 2. First aid hose reel and hydrant systems are not provided.
- 3. MOEFA is not provided.
- 4. Terrace pump of 450 LPM is not provided.
- 5. Overhead fire water tank of capacity20000 Ltr is not provided.
- 6. Exit signages found inadequate.
- 7. There shall be no entry from guest house to the restaurant.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings for further consideration in the matter.

Yours faithfully

DIRECTOR

Delhi Fire Service

Copy to :-

The Joint Commissioner of Police (Lic.), Licensing Unit,

Defense Colony Police Station, New Delhi