

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/NDZ/2022/College/26

Dated:- 4.06.2022

To

The Executive Engineer,
Delhi Tourism & Transportation
Development Corporation Ltd.,
Srinivaspuri, Lajpat Nagar,
Near Cambridge School, Ring Road,
New Delhi - 110065.

Sub:- Regarding issuance of NOC/FSC in r/o Dr. H.J. Bhabha Industrial Training Institute, Mayur Vihar Phase-1, Delhi.

Sir,

This has reference to your letter No. 25(07)/DTTSC/Engg./EE(E)/2022-23/70 dated 07/05/2022 on the subject cited above. You are requested to submit the compliance of said letter no. F6/DFS/MS/BP/2017/11 dated 06.01.2017 (photocopy enclosed).

Yours faithfully

(**Dr. S.K. Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

The Executive Engineer (Civil), Education Project Division-I, Vikas Bhawan-2, Govt. of NCT Delhi, Civil Lines, Delhi – 54.

910

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI DIRECTORATE OF DELHI FIRE SERVICE: NEW DELHI - 119901.

NO. F.6/. DFS /MS/BP/2019 / 11

Dated

06-01-17

Executive Engineer(Civil)
Education project division -1
Vikas Bhawan-2
Govt. of NCT Delhi, Civil Lines
Delhi-54

Sub:- Clearance of building plans from fire safety point of view in r/o East Delhi Campus of Delhi Technological University (DTU) at ITI Mayur Vihar Delhi -91

Please refer to your letter NO. 54(9)/EE/Edu. project Div.-1/PWD dated 23.12.16 on the subject cited above. In this connection, it is to inform you that the above referred building plans have been scrutinized by this department from fire & life safety point of view and following shortcomings are observed.

- 1. Fire tower is not proposed as per clause 9.3.13 of UBBI-2016.
- 2. Alternate exit to pump house is not proposed as per clause 7.10 of UBBI-2016.
- 3. Refuge area is not proposed as per clause 9.3.6 of UBBL-2016.
- 4. Fire control room is not proposed as per clause 9.3.10 of UBBL-2016.
- 5. 02 meter door width in the lecture theatre/seminar hall is not proposed.
- 6. Electrical /AHU room in H-5 is not protected fire check door.
- 7. Fire fighting arrangements are not marked on the plans as per NBC part-4/UBBL-2016.
- 8. Smoke management system are not proposed as per NBC part-4.

In view of above, the building plans are hereby returned to rectify the above shortcomings and resubmit for further consideration in the matter.

Encl. As above

Yours faithfully

(Virendra Singh - Dy. Chief Fire Officer 011 - 23412025

174