



No.F6/DFS/MS/School/SZ/2022/364

Dated: 30/06/2022

To

The Principal,
S.D.M.C. Pratibha Vidyalaya,
Jaitur No.1-I, Badarpur, New Delhi-44.
(1st shift ID- 1958118 & 2nd shift ID -1958119).

Sub:- Regarding renewal of Fire Safety Certificate in respect of **S.D.M.C. Pratibha Vidyalaya, located at Jaitur No.1-I, Badarpur, New Delhi-44. (1st shift ID- 1958118, 2nd shift ID - 1958119).**

Sir,

With reference to your letter no. nil dated 25.05.2022 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 16.06.2022 in the presence of Mr. Prem Singh Bharti, Principal and it was observed that the building is comprised of three blocks (Ground + 1 upper floor, Ground + 1 upper floor & Ground + 02 upper floors). During the inspection following shortcoming were observed:-

1. First aid hose reels found non functional.
2. Fire pump having capacity 450 LPM found non functional.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(Sunil Chawdhary)

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
2. The Principal, S.D.M.C. Pratibha Vidyalaya, located at Jaitur No.1-I, Badarpur, New Delhi-44. (2nd shift ID -1958119).