

No.F6/DFS/MS/ Business /SZ/2022/ 1648

Dated: 06/07/2022

То

M/s Center for Development of Advanced Computing, Plot no 20, Block no. FC-33, Institutional Area, Jasola, New Delhi.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Center for Development of Advanced Computing locoed at Plot no 20, Block no. FC-33, Institutional Area, Josola, New Delhi.

Sir,

With reference to your email dated 08.06.2022 on the subject cited above, it is informed that the said building was inspected by Assistant Divisional Officer (M. Road) from this department on 21.06.2022 in the presence of Mr. Manoj (Sr. Admin Officer) & Mr. Debashish (Civil Project Engineer) and it was observed that the building is comprised of 02 Basement (Lower basement & Upper basement) + Stilt + 06 upper floors. During the inspection the following shortcomings were observed: -

- 1. Fire check door (FCD) found removed from staircase and lift lobby at 6th floor.
- 2. Vertical and horizontal openings not sealed.
- 3. Access to the 3rd fire exit passing through occupied area at ground, 2nd & 3rd floor.
- 4. No ventilation system in common area at all floors.
- 5. Internal hydrants found non functional.
- 6. Pressurization system not synchronized with MOEFA/ Automatic Fire Detection and Alarm System (ADAS).
- 7. Supply from overhead tank closed by butterfly valve at multiple points.
- 8. Fire pumps are not on auto mode.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfull Delhi Fire Se

Copy to:-

 The Executive Engineer (Building), South DMC, 9th floor, Dr. SPM Civic Centre, JLN Marg, New Delhi.