



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/2022/ School/ 373

Dated: 6 / 7 /2022

The Principal, M.C. Primary Boys School, Nihal Vihar-II, Delhi-110041

## Subj.:- Regarding issuance of Fire Safety Certificate in r/o M. C. Primary Boys School (ID-1354536), Nihal Vihar-II, Delhi-110041.

Sir.

Please refer to your letter no. nil dated 31.05.2022 on the subject cited above. In this connection it is to inform you that the said building have been inspected by the officer concerned of this department on 24.06.2022 in presence of Sh. Satish Kumar (Incharge, Evening shift) to check compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/School/2013/1904 dated 29.07.2013.

During inspection, it have been observed that the shortcomings issued by this department vide above said letter has not been fully rectified yet.

In view of the above shortcomings, Fire safety Certificate cannot be grant at this stage. You are advised to rectify the above mentioned shortcomings under intimation to this department for taking further necessary action.

Yours aithfully,

(Dharampal Bhardwaj)
Dy. Chief Fire Officer

(West Zone

Copy to :-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi –

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F6/DFS/ans/school/2013/1804 Dated 28/07/13

To

The Principal, Nigam Prathmic Vidyalaya, Nihal Vihar, Nangloi, Delhi-110041.

Sub:- Inspection report in respect of Nigam Prathmic Vidyalaya, Nihal Vihar, Nangloi, Delhi-110041, from Fire Safety point of view.

Sir,

With reference to your letter No. Nil dated 07.02.2013 on the subject noted above it is informed that the said school premises was inspected by the officer concerned of this department on 03.07.2013 in the presence of Sh. Kangan Sehrawat (Principal of the School).

During the course of inspection it was observed that the school premises comprised of ground floor only having plot area 1100yard<sup>2</sup> & covered area 700yard<sup>2</sup> with 10 class rooms and 751 students. Fire Safety arrangements such as fire extinguishers were found provided.

The following shortcomings were observed during the time of inspection:-

- Premises is not approachable to Fire Units. (Two lengths of Hose is not sufficient to reach the school gate.)
- 2. Door size is 85cms against requirement of 1.00Mtr.

The School premises is not meeting the requirement of Fire & Safety guidelines issued by the Directorate of Education circular dated 01.03.2011,

In view of above, Fire Safety Certificate from Fire & Safety point of view cannot be considered at this stage.

(VIPIN KENTAL)

Dy. Chief Fire Officer,
Delhi Fire Service.
dcfowz.dlfire@nic.in
Ph: 011-23842505

Copy to:-

 Director of Education, North Delhi Municipal Corporation, Dr. S.P.M., Civic Center, Minto Road, New Delhi-110002.