

4317

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2022/SZ/College/30
To

Dated: 08/07/2022

The Joint Director (L&T)
Building Section,
DDA, INA Vikas Sadan,
New Delhi

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o AADI, (Action for Ability Development and Inclusion) at Plot No 2, Balbir Saxena Marg, Hauz Khas, New Delhi 110016.

Sir,

This has reference to with Gmail of dated 30/05/2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 27/06/2022 and observed that the shortcoming intimated vide letter of even no 486 dated 28/02/2014 has not been complied yet. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit. The action taken report in this concerned may also be forwarded to this department.

Yours faithfully,



(SUNIL CHAUDHARY)
DY. CHIEF FIRE OFFICER (SZ)
DELHI FIRE SERVICE

Copy to:-

1. Ms. Seema Ghosh, Action for Ability Development and Inclusion, (AADI) Plot No 2, Balbir Saxena Marg, Hauz Khas, New Delhi 110016

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

E-mail: Gargatul@hotmail.com, Tel. No. 26189168

No. F6/DFS/MS/2014/486

Dated: 22/02/14

To

Madhu Grover,
Dy. Executive Director,
Plot No. 02, Balbir Saxena Marg,
Hauz Khas, New Delhi-110016.

C/S12

Sub.: Regarding renewal of fire safety certificate in respect of AADI (Action for Ability Development and Inclusion), Plot No. 02, Balbir Saxena Marg, Hauz Khas, New Delhi.

Sir,

Please refer to your letter No. nil dated 22-10-2013 on the subject cited above. In this connection, it is to inform you that the inspection of the said building has been carried out by the officer concerned of this department on 12-02-2014 and observed that the said building is comprised of lower ground floor, ground floor and two upper floors, serving with 02 nos. of staircases, 01 ramp & 01 lift and located on motarable road. Fire safety arrangements such as access, under ground water static tank, draw off connection, fire service inlet, sprinkler system in lower ground floor, yard hydrants, internal hydrant, hose reel, overhead water tank, fire pump, and different types of fire extinguishers etc found provided. However following shortcomings were observed: -

1. Hose reel found non-functional due to the damage of rubber pipe.
2. Terrace pump found non functional and Connection with D.G. set found defective.
3. MCP found removed.
4. Detection system & MCP provided in one portion of basement floor found non-functional.
5. Exit signs are missing at some places.
6. Only 10,000 lts overhead water storage tank is provided for fire fighting. Additional 10,000 lts over head water tank found removed.
7. One exit door at basement floor found blocked. It should be kept always in open position for evacuation in an emergency situation.
8. P.A system found removed.

In view of the above, the said building is not safe from fire safety & means of escape point of view and fire safety certificate cannot be renewed at this stage.

Yours faithfully

(ATUL GARG)
Dy. Chief Fire Officer
Delhi Fire Service

22/02/14