

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/NDZ/2022/GM/580

Dated:-13/7/2022

To

The Manager  
M/S Everest Palace Guest House,  
8244, Gali No.6, Arakashan Road,  
Pahar Ganj, New Delhi.

Sub: Regarding issuance of FSC in r/o M/S Everest Palace Guest House, 8244, Gali No.6, Arakashan Road, Pahar Ganj, New Delhi.

Sir,

This has reference to Online id no.2022051710453 dated 17.05.2022, on the subject cited above. In this connection, it is to inform you that the site was inspected by the officer concerned of this department on 29/06/2022 in the presence of **Manager** and following shortcomings were observed:-

1. Smoke management system not provided as per gazette notification dated 27.05.2019.
2. CO Detectors are not provided as per gazette notification dated 27.05.2019.
3. Hose reel found nonfunctional.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings for further consideration in the matter.

Yours faithfully,

*(Signature)*  
12/07/22

(S.K. Dua)

Dy. Chief Fire Officer  
Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defense Colony Police Station, New Delhi.