

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/GH/NDZ//2022/ 533

Dated: 7/ 7/2022

To

The Joint Commissioner of Police (Lic.),
1st Floor, Police Station Defence Colony,
New Delhi.

Sub: Regarding issue of Fire Safety Certificate (FSC) in r/o **M/s Shyama Inn** located at
5050/12, Netaji Subash Marg, Daryaganj, Delhi - 06.

Sir,

This is in reference to online application Id no.2022060612157 dated 06.06.2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 29.06.2022 and observed that the shortcomings intimated vide letter of even No.F6/DFS/MS/GH/NDZ//2022/405 dated 30/05/2022 have not been complied yet. (Copy enclosed for ready reference).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Encl: As above.

(S. K. Dua)

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

The Manager,
M/s Shyama Inn at 5050/12, Netaji Subash Marg, Daryaganj, Delhi - 06.

239

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2022/ 405

Dated: 30/05/2022

To

The Joint Commissioner of Police (Licensing),
1st Floor, Police Station Defence Colony,
New Delhi.

Sub: Regarding renewal of Fire Safety Certificate in respect of **M/s Shyam Inn, 5050/12, Netaji Subhash Marg, Daryaganj, Delhi-06.**

Sir,

With reference to online application I.D. no. 2022050409377 dated 04.05.2022 on the subject cited above, it is informed that the guest house was inspected by Assistant Divisional Officer (SPM) from this department on 19.05.2022 in the presence of Mr. Ajay Singh (Manager) and it was observed that building is comprised of Ground + Mezzanine + 03 upper floors. During inspection, following shortcomings were observed:

1. Fire check door not provided required as per gazette notification dated 27.05.2019.
2. CO detectors not provided required as per gazette notification dated 27.05.2019.
3. First Aid Hose reel found non functional.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(Dr. S.K. Tomar)

Dy. Chief Fire Officer

Tel: 011-23412025

Copy to:-

The Licensee, M/s Shyam Inn, 5050/12, Netaji Subhash Marg, Daryaganj, Delhi-06.

27/5