



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE  
NEW DELHI

No. F6/DFS/MS/2022/SZ/ Cans/ 1823

Dated: 20/07/2022

To,

Sh. Dharam vir Sardana (President), <unitedcghsdwarka@gmail.com>  
United C.G.H.S Ltd.  
Plot No 34, Sector - 4, Dwarka,  
New Delhi - 110078.


Subject: Renewal of Fire Safety Certificate in r/o United C.G.H.S Ltd. Located at Plot No 34, Sector - 4, Dwarka, New Delhi - 110078.

Sir,

Please refer to your Email Dated 20-06-2022 on the subject mentioned above. In this connection it is submitted that that the above said premises was visited by the officer concerned of this department on 11/07/2022 in the presence of Sh. Ganesh to see the compliance of the shortcomings communicated vide this office letter no. F.6/DFS/MS/SZ/2022/1298, dated 07/06/2022 and found that the shortcomings are still not complied. You are requested to comply the shortcomings under intimation with this department.

In view of the above FSC from fire safety point of view cannot be considered at this stage.

Yours faithfully,

  
(Atul Garg)  
Director,  
Delhi Fire Service.

Copy to:- 1. The Joint Director, DDA, Vikas Sadhan INA, New Delhi

C/116

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE  
NEW DELHI

No.F6/DFS/MS/SZ/2022/1298

Dated: 07/06/2022

To,

Sh. Dharam vir Sardana (President), <unitedcghsdwarka@gmail.com>  
United C.G.H.S Ltd.  
Plot No 34, Sector – 4, Dwarka,  
New Delhi – 110078.

Subject: Renewal of Fire Safety Certificate in r/o United C.G.H.S Ltd. Located at Plot No 34, Sector – 4, Dwarka, New Delhi – 110078.

Sir,

Please refer to Email dated 02/05/2022 on the subject mentioned above. In this connection it is to inform you that the inspection of the premises was carried out by the officer from this department on 21/05/2022 in the presence of Sh. Dharam vir Sardana (President) for the renewal of fire safety certificate.

During course of inspection the following shortcomings were observed:

1. The internal road found encroached due to planters etc.
2. Hose reel hose & internal hydrant found nonfunctional.
3. Yard hydrants found removed.
4. MOEFA found nonfunctional.
5. PA system found nonfunctional.
6. Pumps provided at ground level found nonfunctional.
7. Exit signage found removed at some places.
8. Communication system & fireman ground switch are provided in the lift but found nonfunctional.

In view of the above shortcomings Fire Safety Certificate can not be considered at this stage.

You are requested to comply the abovementioned shortcomings under intimation to this department.

Yours faithfully,

(Atul Garg)  
Director

Delhi Fire Service

Copy to:- The Joint Director, DDA, Vikas Sadan, INA, New Delhi.

File  
00  
00