

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE  
NEW DELHI

No. F6/DFS/MS/SZ/2022/ 1838

Dated: 21/07/2022

To,

The Administrative Officer (J),  
Office of Ld. District & Session Judge (S-W),  
Dwarka Court,  
New Delhi.

Subject: Inspection report/NOC in r/o District Court, Located at Sector -09, Dwarka, New Delhi

Sir,

This has reference to meeting held on dated 11/07/2022 at 4 PM under chairmanship of Ld. ADJ, Dwarka Courts on the subject cited above. In this connection it is to inform you that the inspection of the Dwarka Court Complex was conducted by a team of officers from this department along with Sh. Mohan Lal (JE, PWD) and following shortcomings were observed:-

1. The 6m wide motorable road all around the building found encroached / blocked.
2. The door closers of Fire check doors in all three buildings were found missing at some places and some fire check doors are found damaged.
3. Major addition /Alteration have been made at second floor in lawyers block and alternate exit has been blocked.
4. Some stairs are found closed in basement.
5. Manual Operated Electric Fire Alarm System, PA system found nonfunctional in all three blocks.
6. Open able windows are found replaced with fixed window in some stairs/ some areas in lawyer block /admin block.
7. Terrace pumps are found removed in lawyers block & terrace fire water tanks were found disconnected from fire fighting system and being used for other domestic purpose in Admin block.
8. The sprinkler system must be extended in lawyers block & Admin block as provided in the court block.
9. The fire pumps are not kept on auto mode.
10. The Hoses & branches are found missing from hose boxes.
11. The length of hose reel must be extended to 30 m so that the hose reel may cover entire area of the floor.
12. Smoke Exhaust system must keep in auto mode and interlinked with MOEFA & detectors and the damaged/ leaking ducts must be repaired/ replaced.
13. Pressurization system provided for lift shafts found nonfunctional and required to be put on auto mode.
14. Lift Signage/floor marking found missing at some places in all blocks.
15. The sprinkler nozzle in conference hall at 7<sup>th</sup> floor must be extended below falls ceiling in court block.
16. Fire control room found locked and the key was not readily available. Fire control rooms shall be manned round the clock.

You are requested to direct the concern officers to comply the abovementioned shortcomings under intimation to this department for further necessary action in the matter/renewal of fire safety certificate.

Yours faithfully,

(Atul Garg)  
Director,  
Delhi Fire Service