

998

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/NDZ/2022/ 605

Dated:-22.7.2022

To

The Manager  
M/S **Hotel Gold Palace, 3385,**  
D.B.G. Road, Karol Bagh,  
New Delhi.

Sub: Regarding issuance of FSC in r/o M/S **Hotel Gold Palace** located at 3385, D.B.G. Road, Karol Bagh, New Delhi.

Sir,

This has reference to Online id no.2022061112573 dated 11.06.2022, on the subject cited above. In this connection, it is to inform you that the site was inspected by the officers concerned of this department on 06/07/2022 in the presence of **Manager** and following shortcomings were observed:-

1. Fire check doors not provided as per gazette notification dated 27.05.2019
2. Smoke management system not provided as per gazette notification dated 27.05.2019.
3. CO Detectors not provided as per gazette notification dated 27.05.2019.
4. Hose reel found nonfunctional.
5. PA System found nonfunctional.

In view of above, Fire Safety Certificate cannot be issued. Therefore, you are requested to rectify the shortcomings for further consideration in the matter.

Yours faithfully,



(S.K. Dua)

Dy. Chief Fire Officer  
Delhi Fire Service

Copy to:-

1. The Addl. Commissioner of Police (Lic.), Licensing Unit, Defense Colony Police Station, New Delhi.