

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

C-34

No.F6/DFS/MS/School/2022/SZ/

460

Dated: 4 / 8 / 2022

To

The Principal,
EDMC Primary School Gonda North, Urdu-1,
B-5, Yamuna Vihar, Delhi-110053.

**Sub.:- Inspection Report in r/o EDMC Primary School Ghonda North, Urdu-1, B-5,
Yamuna Vihar, Delhi-110053.**

Sir,

Please refer to your letter No. Nil dated 15/07/2022 and outdoor diary No. 3448 dated 15/07/2022 on the subject cited above. In this connection it is to inform you that the premises was visited by officer of this deptt. on dated 20/07/2022 in presence of Smt. Seema Nigar (Principal) and observed that management has still not complied the shortcomings issued vide letter No. F6/DFS/MS/School/2021/NDZ/518 dated 27/09/2021. *(Copy enclosed)*.

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Enclosed: as above

Yours faithfully,

(Signature)
(S.K. DUA)

DY. CHIEF FIRE OFFICER (NDZ).

Copy to:-

1. The commissioner, MCD, Civic Centre, J.L.Nehru Marg, New Delhi-110002.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F6/DFS/MS/School/2021/NDZI/ 518

Dated: 27/09/2021

To,

The Principal,
EDMC Primary School Gonda North, Urdu-I,
B-5, Yamuna Vihar,
Delhi 110053

Sub:- Regarding Issuance Fire Safety Certificate.

Sir,

This is in reference to your Email. dated 13/08/2021 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mr. Masroor Ahmad (Incharge) of the School on 26/08/2021. During the course of inspection, the following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

1. Fire extinguishers not provided.
2. First-Aid hose reels (02 nos.) at each floor not provided.
3. A fire pump having 450 LPM output at 40 meters head not provided.
4. Over Head water storage tank 10,000 liters capacity exclusively for fire fighting not provided at terrace.
5. Exit Signage not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

(Atul Garg)
Director

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92