

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIH HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



Dated: 28 07 2022

No. F6/DFS/MS/School/SZ/2022 439

То

The Principal (1<sup>st</sup> & 2<sup>nd</sup> Shift), S.D.M.C Primary School, Zakir Nagar-I, Batla House, Jamia Nagar, Central Zone, New Delhi-25, School ID no. 1958057 & 1958058.

## Sub: - Regarding renewal of Fire Safety Certificate in r/o S.D.M.C Primary School located at Zakir Nagar-I , Batla House, Jamia Nagar, Central Zone, New Delhi-25 (School ID no. 1958057 & 1958058).

Sir/Madam.

With reference to letter no. nil dated 13.04.2022 on the subject cited above, it is informed that the School building has been inspected by the Assistant Divisional Officer (M. Road) from this department on 19.07.2022 in the presence of Mrs. Shabnam Idrees (Incharge), and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/2013/916 dated 07.03.2013 & 04.02.2014 (Photocopy enclosed) has not been rectified till date. The management is requested to rectify the shortcomings at the earliest.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully.

(Sunil Chawdhary) Dy. Chief Fire Officer Delhi Fire Service

## Copy to:-.

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.

## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI** HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/School/2013/ 9/6

Dated: 07/03/13

То

The Principal, M.C. PrimaryModel School, Zakir Nagar (Hindi), Batla House, New Delhi-110025

Sub: - Reg. Fire Safety Certificate in r/o M.C. PrimaryModel School,Zakir Nagar(Hindi) Batla House, New Delhi-110025

Sir,

This has reference to the subject mentioned above. In this regard, the school premises was visited by officer concerned of this department on 20/02/2013 in the presence of Sh. Mausam Ali, Principal of the school. During the inspection, it was observed that school building comprised of comprised of ground plus three upper floors.

The shortcomings observed are as below: -

- 1. Fire extinguisher provided are inadequate. Four more fire extinguishers to be provided.
- 2. First-Aid Hose reel not found provided.
- 3. Internal hydrant with hose box not provided.
- 4. Terrace level pump not found provided.
- 5. Over-head tank exclusively for fire fighting capacity 10,000 ltrs not provided.
- 6. Exit signage not found provided.
- 7. Standby power supply not found provided.

In view of the above shortcomings, Fire Safety Certificate can not be considered at this stage. You are advised to get the above mentioned shot-comings rectified under intimation to this department.

Yours faithfully, Dy. Chief ire Officer ire Service

## Copy To: -

1. The Dte. of Education, MCD, Civic Centre, New Delhi.