

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/NDZ/ 447

Dated: 4 / 8 /2022

To

The Manager,
Nav Jeevan Adarsh Public School,
C-5, Yamuna Vihar, Delhi-110053.

Sub.:- Inspection Report in r/o Nav Jeevan Adarsh Public School, C-5, Yamuna Vihar, Delhi-110053.

Sir,

With reference to your letter No Nil outdoor diary No. 1922 dated 30/05/2022 on the subject noted above. In this connection, it is to inform you that the said building premises was inspected by the officer concerned of this department on 20.07.2022 in the presence of Sh. Sumit Bansal (Manager).

During the course of inspection it was observed that the building premises is comprised of Ground plus two upper floors only.

However following shortcomings were observed during the time of inspection:-

1. Hose Reel Hose provided but nonfunctional.
2. Fire Pump of 450 Lit/min capacity provided but nonfunctional.
3. Overhead tank capacity of 5,000 ltr is provided against requirement of 10,000 ltrs.
4. Exit Signage not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(S.K. Dua)

Dy. Chief Fire Officer.

Copy to :-

1. Director of Education, Old Secretariat, Civil Lines, Delhi-110054. 