

18

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI- 110001

No. F6/DFS/MS/School/2022/SZ/ 501

Dated: 23/8/22

To,


The Manager,
St. Bharti Public School,
2B-3A, Vikas Nagar, Hastal,
Uttam Nagar New Delhi-110058

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o St. Bharti Public School, 2B-3A, Vikas Nagar, Hastal, Uttam Nagar New Delhi-110058

Sir,

This has reference to your letter No. Nil dated 15/07/2022 the subject captioned above. In this connection, it is to inform you that the above mentioned school premises was inspected by the officer concerned of this department on 03/08/2022 in the presence of Mr. Sureshwar Dutt (Manager) to verify the compliance of shortcoming already communicated by this department vide letter no.F6/DFS/MS/2015/School/334 dated 17/02/2015 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully


(Sunil Chawdhary)

Dy.Chief Fire Officer
Delhi Fire Service



Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054

(With a request to take further action as school does not have fire NOC)

c-24

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001
E-mail : gargatul@hotmail.com Ph. 011-26189168

No: F.6/DFS/MS/2015/*school/334*

Dated: 17/02/15

To

The Manager,
St. Bharti Public School,
2B-3A, Vikas Nagar,
Hastsal, Uttam Nagar,
New Delhi-110059.

Sub: - Regarding renewal of Fire Safety Certificate in r/o St. Bharti Public School, 2B-3A, Vikas Nagar, Hastsal, Uttam Nagar, New Delhi-110059.

Sir,

Please refer to your letter No. Nil, dated 05.01.2015 on the subject cited above. In this connection, it is to inform you that the inspection of above said premises has been carried out by officer concerned of this department on 03.02.2015 to see the compliance of the requisite Fire Safety measures. Mr. Sarveshwar Dutt (Manager) was present at the time of inspection.

During the course of inspection it was observed that the school building comprised of ground floor plus two upper floors. The upper floors are served by single staircase having width 92 cms. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The building is located on the road approachable to the fire fighting vehicles., but the building does not meet the required norms in the light of Delhi Fire Service Act 2007, and Rule 2010, provisions contained in NBC of India (part-IV) due to the following shortcomings: -

1. The width of the staircase is to be increased up to 150 cms.
2. Hose Reel Should be provided as per IS 884 : 1985.
3. Overhead water storage tank capacity 10000 Ltrs is to be provided.
4. Fire pump of 450 LPM, 40 mtrs head is to be provided.
5. Exit signs are not provided in the school building.
6. Two Co2 type Fire Extinguishers of 4.5 kg/2.2 kg capacity each (ISI marked) and four ABC type Fire Extinguishers of 05 kg capacity each (ISI marked) are not provided in the school building.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully

(Signature)
Atri Garg
Dy. Chief Fire Officer
Delhi Fire Service

(Signature)
13/2/15