

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/SZ/2022/ 507

Dated: 🔰 Ч

1082022

To

The Principal,
Tushar Modern School,
Gali No.-07, Lakhpat Colony Part-1,
Molarband School Road, New Delhi-110044.

Sub:- Regarding renewal of Fire Safety Certificate in respect of Tushar Modern School, located at Gali No.-07, Lakhpat Colony Part-1, Molarband School Road, New Delhi-110044.

Sir,

With reference to your letter no. TMS/Fire Safety-22 dated 12.05.2022 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 29.07.2022 in the presence of Head Mistress and it was observed that the school building is comprised of Ground + 1 upper floors. During the inspection following shortcomings were observed:-

- 1. Hose reel found not provided
- 2. Fire pump having capacity 220 LPM & head 40 mtrs. not provided.
- 3. Overhand tank capacity 2,500 liters not provided for fire fighting.
- 4. Exit signages not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Delhi Fire Service

Copy to:-.

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.