

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/NDZ/2022/EH/560

Dated: 06.09.2022

6/09/2022

To

The Manger,
M/s Bikanerwala Foods Pvt. Ltd,
Handicrafted Bhawan, 1st floor,
Baba Khadak Singh Marg,
Connaught Place, New Delhi.

Sub: Application for issuance of fire safety certificate in respect of **M/s Bikanerwala Foods Pvt. Ltd,** located at Handicraft Bhawan, 1st floor, Baba Khadak Singh Marg, Connaught Place, New Delhi.

Sir,

This has reference to your mail id <timeoffice@bikano.com> dated **09.08.2022**, on the subject cited above. In this regard, it is to inform you that the site was visited by officer concerned of this department on dated **25.08.2022** in presence of **Manager** and observed that shortcomings issued earlier vide letter no. **F6/DFS/MS/NDZ/2021/96** dated **19/02/2021** (copy enclosed) have not been complied so far.

In view of above, FSC can't be issued till the compliance of all the shortcomings issued vide aforesaid letter.

Encl: As above.

Yours faithfully,


(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to :

1. The Addl. Commissioner of Police (Lic.) First floor, PS Defense Colony, New Delhi.

DELHI
C-51
C-63
C-47
2182

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/NDZ/2021/ 96

Dated: 19.02.2021

To

The Deputy Commissioner (Licensing)
1st Floor, Police Station Defence Colony,
New Delhi.

Subject:- Online Application ID No.- 2020091607007 in r/o M/s Bikanerwala Foods Pvt. Ltd. located at Rajiv Gandhi Handicrafts Bhawan, Baba Kharak Singh Marg, New Delhi.

Sir,


This has a reference to online application ID No.- 2020091607007 dated 16/09/2020 received on the subject cited above. In this connection, it is to inform you that the subject cited restaurant has been inspected by the officers concerned of this department on 11.02.2021 in presence of Mr. Ritesh (Manager). During inspection following shortcomings were observed at site

1. Hose reel hose found nonfunctional.
2. Sprinkler system found nonfunctional.
3. Hydrant found nonfunctional.
4. Fire pumps found nonfunctional.
5. Main pipe line found damaged.

Further, as built plans is not signed by the empaneled engineer /registered architect and owner /occupier of the building.

In view of above, the Fire Safety Certificate (FSC) cannot be issued. Therefore, you are requested to direct the applicant to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully


(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service



Copy to:-

The Manager ,
M/s Bikanerwala Foods Pvt. Ltd.,
Rajiv Gandhi Handicrafts Bhawan,
Baba Kharak Singh Marg, New Delhi.