



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No: F.6/DFS/MS/School/2022/SZ/ 529

Dated: 5/8/22

To,

The Principal, Govt. Boys Sr. Sec. School, Dhansa, New Delhi-110073.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. Govt. Boys Sr. Sec. School, Dhansa, New Delhi-110073

Sir,

This has reference to your Letter No. 54 (SPS School) PWD Edu. Sub-Divn M1-1(N)/2022-23/Camp(01) Dated- 20/04/2022 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 16/08/2022 to verify the fire safety arrangements in accordance with the Rules. At the time of inspection Mr. Manoj Singh (Constructor) was present and it was observed that the school building is comprised of ground plus three upper floors and have following shortcomings.

- 1. Hose reels are provided but not functional.
- 2. Fire pump having 450 lpm provided but not functional.
- 3. Exits signage's are provided but not sufficient.

In view of above, issuance of fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully **Delhi Fire Service** Jon.

Copy to: -.

- 1. The Executive Engineer (E), Division M1, ITI Campus Pusa New Delhi.
- 2. M/s Sunehari Bagh Builders Pvt. Ltd.,603, Anushika Tower, G35 Mall, Sector-11, Rohini, Delhi-110085.