

253



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आजादी का
अमृत महोत्सव

No. F6/DFS/MS/School/SZ/2022/729

Dated: 02/09/2022

To

The Joint Commissioner of Police: Licensing.
1st Floor, P. S Defence Colony,
New Delhi.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s Karon Hotel (Guest House) located at 61, Ring Road, Lajpat Nagar- II, New Delhi.

Sir,

With reference to letter no. nil dated 04.08.2022 on the subject cited above, it is informed that the guest house was visited by the Assistant Divisional Officer (M. Road) from this department on 25.08.2022 in the presence of Manager and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/GH/SZ/2022/565 dated 12.07.2022 (Photocopy enclosed) has not been rectified completely till date.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Sunil Chawdhary)

Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Licensee, M/s Karon Hotel (Guest House) located at 61, Ring Road, Lajpat Nagar-II, New Delhi.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/50
आज़ादी का
अमृत महोत्सव

No.F6/DFS/MS/GH/SZ/2022/ 565

Dated 12/07/2022

To

The Joint Commissioner of Police: Licensing,
1st Floor, P. S Defence Colony,
New Delhi

Sub:- Regarding grant of Fire Safety Certificate in r/o M/s Karon Hotel (Guest House) located at 61, Ring Road, Lajpat Nagar III, New Delhi.


Sir,

With reference to online application no. 202251810627 dated 21.06.2022..on the subject cited above, it is informed that the guest house was inspected by Assistant Divisional Officer (M. Road) from this department on 28.06.2022 in the presence of Sri Deepak Bakshi (Manager) and it was observed that the building is comprised of Basement + Ground + 03 upper floors. Following shortcomings were observed during the inspection:

1. Fire check doors have not been provided at all floors including basement.
2. Ventilation provisions are inadequate in the basement and upper floors.
3. Hose reel system found non functional.
4. CO detector system not provided.
5. Manually Operated Electrical Fire Alarm (MOEFA) found non functional.
6. Sprinkler system found removed in front portion of the basement.
7. Boosting arrangements found non functional.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Local Authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

The Licensee,

M/s Karon Hotel (Guest House) located at 61, Ring Road, Lajpat Nagar III, New Delhi.

7/50
12/07/2022