297 ROCIA

N. A.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2022 / 541

Dated: 06/09/2012

To.

The Manager, Rajkumar Model School, A-227, Shastri Nagar, New Delhi- 110052.

Subject: - Regarding renewal of Fire Safety Certificate in r/o Rajkumar Model School, A-227, Shastri Nagar, New Delhi- 110052.

Sir.

Please refer to your letter no. Nil dated Nil received through outdoor diary no. 3221 dated 11/07/2022 on the subject cited above. In this connection, it is to inform you that this department has never issued any Fire Safety Certificate as per the record available. This department has issued shortcomings vide this department letter no. F6/DFS/MS/School/2015/2110 dated 15/09/2015.

In view of above, the application for issuance of Fire safety Certificate can't considered at this stage. You are requested to re apply again after compliance of the shortcomings issued by this departments vide letter No.F6/DFS/MS/School/2015/2110 dated 15/09/2015. (Copy enclosed)

Yours Faithfully

Director Delhi Fire service

Copy to:

Directorate of Education Old Secretariat Delhi – 110054.

12/9/22

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

To. \$6 (DES/ ans/ & charol/ 2110

Dated: 15/08/15

The Principal, Rajkumar Model School, A-227, Shastri Nagar Delhi.110052.

Sub:- Inspection report in respect of Rajkumar Model School, A-227, Shastri Nagar Delhi.110052.

Sir,

Please refer to your letter no. nil dated 06/07/2015 on the subject captioned above. In this connection it is to inform you that the premises was visited by officer of this department on10/08/2015. During course of inspection the following shortcomings were observed:

- 1. Width of staircase for upper floors is less than 1.5 mtr. The width of staircase must be increase to 1.5mtr or an additional staircase of not less than 75 cm should be provided.
- Only one staircase for basement of 1.2 mtr width is provided against required two staircases of 1x1.5m and 1x100cm.
- 3. Fire Extinguishers are not provided.04 Nos Fire Extinguishers of DCP Type/ Co2 type2.5 Kg/5 Kg Capacity are required to be provided
- 4. Width of the class room doors is less than required 1mtrs clear width.
- 5. Hose Reel hose of 30 mtrs length at each floor not provided.
- 6. Terrace pump of 450lpm not provided.
- 7. Over Head tank of 10000 ltrs capacity not provided.
- 8. Exit signage not provided.
- 9. Use of Basement must be as per BBL 1983.

The Premises is covered under Delhi Fire Service Act 2007 and Rule 2010. The year construction of the school to be informed by the school and supporting documents from any govt, department may be furnished.

In view of the above shortcomings Fire Safety Certificate can not be considered at this stage. You are requested to comply the abovementioned shortcomings with in a period of 90 days time under intimation to this department. The period shall be at your risk and cost.

Yours faithfully,

(Vipin Kental)
Dy. Chief Fire Officer.
PH. 011-23846352