

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/School/2022/SZ/554

Dated: 09/09/2022

To

Durga Public School,  
A-13/15 Durga Vihar,  
Devli, New Delhi 110062

**Sub:** Regarding issuance of Fire Safety Certificate (FSC) in r/o Durga Public School, at A-13/15 Durga Vihar, Devli, New Delhi 110062.

Sir,

This has reference with letter received through outdoor diary no 3773 dated 25/07/2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 26/08/2022 and observed that the shortcoming intimated vide letter of even no 5729 dated 20/09/2019 has not been complied yet. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,



**(SUNIL CHAWDHARY)**  
**DY. CHIEF FIRE OFFICER (SZ)**



C8

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/School/2019/SZ/ 5729

Dated: 20/9/19

To

The Principal,  
Durga Public School,  
A-13/15, Durga Vihar, Devli  
New Delhi-110062

Sub.:- Renewal of Fire Safety Certificate.

Sir,

This has reference to your letter No. Nil dated 24/07/2019 on the subject cited above. In this connection the school premises was inspected by the officer concerned of this department on 12/09/2019 in the presence of Mrs. Usha Agarwal Sandeep (Principal). During the course of inspection it was observed that school building is comprised of ground plus three upper floors (school running at ground and first floor).

The shortcomings observed are as below: -

1. One staircase required with the width of 0.75m found removed.
2. First aid hose reel provided but found non-functional.
3. Terrace level pump capacity 225 LPM with 25m head found non-functional and not provided on auto mode.
4. Overhead water tank of 2,500 liters capacity for firefighting is not provided at terrace.
5. Exit signage not provided at conspicuous places at every floor.

In view of above shortcomings, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further action in the matter.

Yours faithfully,



(Rajesh Panwar)  
Dy. Chief Fire Officer  
Tel. 011-26189168

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.