

75
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
CJ

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

75
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
CJ

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/EH/2022/SZ/ 566
To

Dated: 12/09/2022

The Dy. Health Officer, (South Zone)
Public Health Department, South MCD,
Green Park, Zone, New Delhi 110016

Sub: Issuance of NOC in r/o M/s Haldiram Marketing Pvt Ltd, Plot No 3, GF, FF & SF, Community Centre, PVR Complex, Saket, New Delhi 110017

Sir,

This has reference to with MHA Portal ID 2022080215652 dated 02/08/2022 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 20.08.2022 in the presence of Md. Harwn to verify the fire safety measures installed in the building and observed that the restaurant is running at Ground plus Two upper floor of the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. Staircases having width of 1.60 m & 1.35 mtr. The minimum widths of two staircases are required 1.50 mtr each as per UBBL-2016.
2. Smoke management system not provided.
3. First Aid Hose Reel not provided.
4. Automatic fire detection & alarming system not provided.
5. The MOEFA system is not provided.
6. Automatic sprinkler system not provided
7. The Internal Hydrant not provided.
8. Electrician Fire Pump capacity 2280 LPM, Diesel Engine Pump 2280 LPM and Jockey Pump 180 LPM not provided.
9. Terrace level Fire Pump capacity of 900 LPM not provided.
10. Underground tank capacity 1, 00,000 ltrs not provided. Overhead tank capacity 10,000 ltrs not provided.
11. Exit Signage not provided.
12. Standby power supply not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

Copy to:-

1. M/s Haldiram Marketing Pvt Ltd, Plot No 3, GF, FF & SF, Community Centre, PVR Complex, Saket, New Delhi 110017