

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/Assembly/2022/SZ/ 2317

Dated: 13/09/2022

To

The Executive Engineer, (Bldg) HQ-1, MCD, 8<sup>th</sup> Floor, Civic Centre, Minto Road, New Delhi 110002

Sub: Issuance of FSC in r/o Gurdwara Sri Guru Singh Sabha (Regd.) at **Plot No 04**, Sector- V, MB Road, Pushp Vihar Sector-5, New Delhi 110017

Sir,

This has reference to your letter received through outdoor diary no 3705 dated 22/07/2022 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 30.08.2022 in the presence of Sh. Charanjeet Singh to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

- 1. There is one staircase having width of 1.50 mtr. The minimum widths of two staircases are required 2.00 mtr each as per UBBL-2016.
- 2. Smoke management system not provided in the building.
- 3. First Aid Hose Reel not provided.
- 4. The Internal Hydrant not provided.
- 5. Terrace level Fire Pump capacity of 450 LPM not provided.
- 6. Overhead tank capacity 10,000 ltrs not provided.
- 7. Exit Signage not provided.
- 8. Standby power supply not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully (ATUL G DIRECTOR

Copy to:-

1. Gurdwara Sri Guru Singh Sabha (Regd.) at Plot No 04, Sector- V, MB Road, Pushp Vihar Sector-5, New Delhi 110017