

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

C75

No. F6/DFS/MS/school/2022/SZ/ 588

Dated: 21/09/2022

To,


The Manager,
M.R. Vivekanand Model School,
Mukhram Park Exten., Tilak Nagar,
New Delhi-110018.

Sub: - Regarding grant of NOC from fire safety point of view in r/o M.R. Vivekanand Model School, Mukhram Park Exten., Tilak Nagar, New Delhi-110018.

Sir,

This has reference to your letter No. MRV/22-23/FS/00134 dated 17/08/2022 on the subject captioned above. In this connection, it is to inform you that the above mentioned school building was inspected by the officers concerned of this department on 08/09/2022 in the presence of Sh. Anil Sharma (Manager) to verify the compliance of shortcoming already communicated by this department vide letter no.F6/DFS/MS/School/2019/SZ/2930 dated 20/05/2019 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully



(Sunil Chawdhary)
Dy.Chief Fire Officer



Copy to:-

The Director of Education,
Govt. Of NCT of Delhi, Old Secretariat,
New Delhi-110054.

G-2

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ /2939

Dated: 20/5/19

To, ✓

The Manager,
M.R. Vivekananda Model School,
Mukhram Park Extn., Tilak Nagar,
New Delhi-110018

Sub: - Regarding issuance of Fire Safety Certificate in r/o M.R. Vivekananda Model School,
Mukhram Park Extn., Tilak Nagar, New Delhi-110018.

Sir,

This has reference to your Letter No. Nil dated 05.02.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 02.05.2019 to see the requisite fire safety measures. Sh. Anil Sharma (Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground plus three upper floors. The upper floors are served by two staircases having width 94 cms & 95 cms. The building is approachable to fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcoming was observed:-

1. The upper floors are served by two staircases having width 94 cms & 95 cms against required two staircases having width 150 cms each.
2. Corridor width is to be increased to 150 cms.
3. Door width is 85 cms against required 120 cms.
4. Hose reel system is not provided.
- ✓ 5. Fire pump having capacity 450 LPM not provided for hose reel system.
- ✓ 6. Overhead water storage tank of 10,000 ltrs capacity not provided for hose reel system.
7. Exit signs are not provided.

- If student capacity is more than 45 in any class room then double door having width 120 cms is required.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)
CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054