## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No. F6/DFS/MS/SZ/2022/ Schoa

Dated: 03/10/2022

-19

To,

Dr. Sheetal Mann (Principal) <modernconventschool@rediffmail.com> Modern Convent School, Sector - 4, Dwarka New Delhi -110078.

Subject: - Issuance of Fire safety Certificate from fire safety & means of escape point of view in r/o Modern Convent School, Located at Sector - 4, Dwarka New Delhi -110078.

Sir,

Please refer to your letter No. MCS/2022/854, dated 30/08/2022 on the subject mentioned above. In this connection it is to inform you that the above said premises was visited by the team of officers concerned of this department on 20/09/2022 in presence of Dr. Sheetal Mann (Principal) to see the compliance of the shortcomings communicated vide this office letter No. F6/DFS/MS/SZ/2022/School/104, dated 14/03/2022 & found that the shortcomings are still not fully complied. You are requested to comply the shortcomings under intimation with this department for further consideration in the matter.

In view of the above Fire Safety Certificate from fire safety point of view cannot be considered at this stage.

Yours faithfully,

Copy to:-

(Atul (Garg)) (Director) Delhi Eire Service

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

## NO. F6/DFS/MS/SZ/2022/School 101

DATED: 14 / 03/2022

-15

To,

Dr. Sheetal Mann (Principal) <modernconventschool@rediffmail.com> Modern Convent School,

Sector - 4, Dwarka New Delhi -110078.

Subject: - Issuance of Fire safety Certificate from fire safety & means of escape point of view in r/o Modern Convent School, Located at Ground+3 Upper Floors Sector – 4, Dwarka New Delhi -110078.

Sir,

Please refer to your Email Dated 18-02-2022 on the subject cited above. In this connection it is to inform to you that the above said building has been inspected by the officer concerned of this department on 24/02/2022 in presence of Dr. Sheetal Mann (Principal).

During the course of inspection followings shortcoming have been observed:-

- 1. The width of entry gate found less than 6mtr.
- 2. Six m internal road around the building found not provided.
- 3. Fire Check Doors found not provided.
- 4. Width of Class room doors are less than 1.2 mtr required width at 4<sup>th</sup> floor
- 5. Smoke management system not interlinked with MOEFA in basement.
- 6. Manually operated fire alarm system (MOEFA) found not provided at 4<sup>th</sup> floor
- 7. Public address system not extended to 4<sup>th</sup> floor.
- 8. Main pump of 2280 lpm jockey pump of 180 lpm and standby pump of 2280 lpm at ground level found not provided.
- 9. Under Ground Fire water storage tank of 50000 litres capacity found provided against required 2,00,000 ltrs capacity.
- 10. Exit signage found not provided.
- 11. Pressurization of Lift Shaft found not provided.
- 12. PA System Panel, Battery backup & Building Floor Plans in fire control room found not provided.

In view of the above, fire safety certificate cannot be renewed. You are advised to rectify the said shortcomings under intimation to this department for taking further necessary action.

Yours faithfully, Delhi Fire

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054