

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/2022/SZ/ 2455
To

Dated: 27/09/2022

Mr. Suresh Goel & Associates,
C-85, Shivalik New Deli 110017

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o New Girls Hostel (Index No-50) Himadri Hostal at IIT Delhi Campus, Hauz Khas, New Delhi

Sir,

This has reference with letter no SGA/03001/Gen/536/4196 dated 09/09/2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 19/09/2022 in the presence of Mr. Rajiv Kumar and observed that the shortcoming intimated vide letter of even no. 469 dated 26/02/2021 has yet not been complied. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,


(ATUL GARG)
DIRECTOR

Copy to

1. Institute Engg., IIT Delhi, , IIT Hauz Khas, New Delhi 110016

P.70

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/2021/SZ/ 469

Dated: 26/02/2021

To

The Executive Engineer (Bldg) HQ,
South MCD, 8th Floor,
SPM Civic Centre, Minto Road,
New Delhi- 110002

Sub - Regarding grant of Fire Safety Certificate in r/o New Girls Hostel (Index No- 50) Himadri Hostel) at IIT Delhi Campus, Hauz Khas, New Delhi.

Sir,

This has reference to Gmail Dated 18/01/2021, on the subject above. In this connection, it is to inform you that the officers concerned of this department along with Mr. Rajiv Aggarwal (Fire Officer) on dated 15/02/2021 to check the compliance of fire safety arrangements from fire safety point of view and following shortcomings were observed:

1. Detection system not functional.
2. Automatic sprinkler system not working in basement.
3. Terrace fire pump & Sprinklers pump not working.
4. Main Electric pump, one Diesel Fire pump & Jockey pump not on auto mode.
5. Exit signs not provided.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under intimation to this department for further action in the matter.

Yours faithfully,


(Atul Garg)
Director



Copy to: -

1. Sh. Rajiv Aggarwal (Fire Officer), New Girls Hostel (Index No- 50) Himadri Hostel) at IIT Delhi Campus, Hauz Khas. New Delhi