

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/Educational /2022/SZ/ 24167  
To

Dated: 28/09/2022

Mr. S Roy (Chief Engineer)  
Indraprastha Institute of Information Technology Delhi,  
IIIT-D Campus, GB Pant Polytechnic Extension,  
Okhla Phase-III, New Delhi 110020

**Sub:** Regarding issuance of Fire Safety Certificate (FSC) in r/o Seminar Block (Lecture Block) Indraprastha Institute of Information Technology, Okhla Industrial Estate, Phase-III, New Delhi 110020.

Sir,

This has reference your Email of dated 03/08/2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 19/09/2022 and observed that the shortcoming intimated vide letter of even no 2313 dated 03/11/2021 has not been complied yet. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

  
(ATUL GARG)  
DIRECTOR

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

Dated: 03/11/2021

No. F.6/DFS/MS/SZ/2021/ 23/3

To

Mr. Sanjay Roy, Chief Engineer (Civil)  
Seminar Block (Lecture Block)  
Indraprastha Institute of Information Technology,  
Okhla Industrial Estate, Phase-III, New Delhi-110020.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o Seminar Block (Lecture Block) Indraprastha Institute of Information Technology, Okhla Industrial Estate, Phase-III, New Delhi-110020.

Sir,

This has reference to the Gmail dated 19/08/2021 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 22.10.2021 in the presence of Sh. Sanjay Roy to check the compliance of fire safety arrangements from fire safety point of view and following shortcomings were observed:

1. Pressurization of lift lobby not provided.
2. There is a material changed at 5<sup>th</sup> floor of the building Vis a Vis approved and existing floor plans. Hence you are hereby advised, either you may restore the earlier composition of 5<sup>th</sup> floor or refer two sets of sanctioned building plans to this department. In case of non availability of sanctioned plans, you may refer two sets of building plans through local authority for further consideration in the matter

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

  
(ATUL GARG)  
DIRECTOR  


Copy to:-

1. The Executive Engineer (Bldg) South Delhi Municipal Corporation, Jal Vihar, Lajpat Nagar, New Delhi 110024